

**RESERVE STUDY**  
Update with Site-Visit/On-Site Review

**Northridge at Danville**  
OWNERS ASSOCIATION

**DRAFT**

Prepared  
**June 4, 2021**

for  
**Fiscal Year 2022**



**John D. Beatty & Company**

14850 Highway 4, Suite A #210 Discovery Bay, CA 94505 (925) 831-1803 Fax (925) 831-2493

## **Contents**

---

<b><u>Reserve Study</u></b>	<b><u>Pages</u></b>
Introduction .....	1
Findings and Disclosures .....	2
Projected Expenditures .....	3 - 11
Funding Plan .....	12 - 14
Component Quantification .....	15 - 17
Accrued Liability .....	18 - 20

Copyright © 1996-2021  
John D. Beatty & Company

## Reserve Study

This report documents the results of an Update with Site-Visit/On-Site Review performed by John D. Beatty & Company for the following Single Family Home Community:

## Northridge at Danyville Owners Association

## Danville, California

It provides an analysis of the repair and replacement requirements for the association's major components and recommends a funding plan to meet those obligations. This study was performed in compliance with California Civil Code sections 4178, 5300, 5550, 5560 & 5565. The intent of this legislation is to insure that the association maintains a plan to meet all future obligations for major component maintenance. The essential elements of this legislation are:

1. Identification of the major components which the association is obligated to maintain
  2. Current estimate of the useful life of each component
  3. Current estimate of the remaining life of each component
  4. Current estimate of the replacement cost of each component
  5. Current estimate of the total annual contribution necessary to maintain the major components
  6. Current estimate of the amount of cash reserves necessary to maintain the major components
  7. Disclosure of the current amount of accumulated cash reserves actually funded
  8. Disclosure of the percentage of reserves actually funded
  9. Disclosure of any determined or anticipated special assessments
  10. A general statement of methodology

## **SCOPE**

This study is aligned with the association's fiscal year and establishes January 1, 2022 through December 31, 2051 as the period of time for which reserve expenditures and reserve fund balances are projected.

## METHODOLOGY

A cash flow methodology was used to determine the annual reserve contribution. The underlying premise of this reserve funding approach is to establish a contribution level that will allow the association to maintain a positive balance in the reserve fund while meeting all anticipated maintenance obligations. The cash flow method allows the association to achieve this goal without the unnecessary overfunding of reserves. Also, as the interest earned on the reserve fund will not totally offset inflation, projections were made using the current inflation factor and an average interest rate on fully insured certificates of deposit.

In preparing this study, a comprehensive list of major components was developed and information was compiled on the type, number, age and cost of each of these components. In gathering this data, certain assumptions were made about costs, conditions, and future events and circumstances that may occur. Some assumptions inevitably will not materialize and unanticipated events and circumstances may occur subsequent to the date of this report. Therefore, the actual replacement costs and remaining lives may vary from this report and the variations could be material. All life expectancies were based on reasonable industry experience for equipment and material and, unless specifically noted, all components were in a reasonable and ordinary condition.

This study was limited to a visual inspection of a reasonable sampling of components, and, as such, did not disturb the major components. Therefore, all common areas for which there is no access without defacement are specifically omitted. However, if sufficient historical data were available that would allow a reasonable projection of future expenditures for any unobservable components e.g., plumbing or electrical wiring, those components could be included in this report.

Since no destructive testing was undertaken, this study does not purport to address any latent and/or patent defects, nor does it address any life expectancies that are abnormally short due to either improper design or installation, or to subsequent improper maintenance. It is assumed that all components are to be reasonably maintained for the remainder of their life expectancy.

For a component to be included in this study, the following criteria must be met:

- 1 . The maintenance of the component is the responsibility of the association;
- 2 . The maintenance of the component is not included in the annual operating budget;
- 3 . The estimated useful life of the component is greater than one year; and
- 4 . The estimated remaining life of the component is less than 30 years.

This study is intended to reflect the estimated replacement cost of the components and is not intended to project the actual cost of the work when performed. This limitation is necessary, as it is virtually impossible to predict with any degree of certainty the myriad factors that will impact costs at a future date. Because of this qualification, it is necessary for the results of this study to be reviewed annually to reflect any meaningful changes in use or significant increases in labor and/or materials costs.

The funding for this study has a threshold margin of 10%. This means that the projected ending balance for each fiscal year is at least 10% of the projected expenditures for the same year. This margin provides a contingency for any unforeseen or out of the ordinary repair or replacement expense. Additionally, it can be used in subsequent years as a source of funds for reallocation of the life cycles should the aging of any components be abnormally accelerated.

#### ***FINDINGS***

The findings of this study indicate that it will be necessary to adjust the annual reserve contribution as indicated on pages 12-14 of this report in order to meet projected expenditures and keep pace with inflation. These findings are based on the following:

1 . Projected reserve fund balance as of January 1, 2022 .....	\$ 316,200
2 . Reserve contribution for fiscal year 2021.....	\$ 42,472
3 . Reserve contribution for fiscal year 2022.....	\$ 48,928
4 . Assumed annual inflation rate .....	3.0%
5 . All "after tax" interest earned on reserve fund investments will be retained in the reserve fund.	

#### ***DISCLOSURES***

John D. Beatty & Company (JDB) verifies herein that any financial or other interests, whether adverse or otherwise, which consultant may have or propose to have in any company, organization, individual, asset or activity has no bearing on the subject matter of this reserve study. Except for the compensation payable to JDB neither JDB nor any of JDB's agents, employees or affiliates shall benefit from our preparation of this reserve study.

This plan provides adequate funds to meet projected expenditures without relying on a special assessments or increases in regular assessments that require a vote of the membership. Based on the assumption that the association will fund reserves in accordance with this plan, which includes those increases indicated above, the percent funded was calculated in the following manner:

<u>Accumulated Cash Reserves (Numerator)</u>	
Projected reserve fund balance as of January 1, 2022 .....	\$ 316,200
<u>Accrued Liability (Denominator)</u>	
(Refer to page 20 of this report)	
Estimate of the amount of cash necessary to repair, replace, restore or maintain the association's major components as of January 1, 2022 .....	\$ 558,199
Percent Funded .....	57%

## Projected Expenditures

RESERVE COMPONENTS	Assumed Annual Inflation Rate.....	3.0%	Repair %	Current Repair/Cost	Estimated Useful Life	Fiscal Year Jan 1 .... Dec 31 .....	(1) 2022	(2) 2023	(3) 2024	(4) 2025	(5) 2026	(6) 2027	(7) 2028	(8) 2029	(9) 2030	(10) 2031
<b>BUILDING EXTERIORS:</b>																
1 - Stucco Siding Paint				22,810	10	1	22,810									
2 - Stucco Siding/Trim Repair	5%			8,502	10	1	8,502									
3 - Exterior Restroom Doors				1,414	25	3										
4 - Wood Doors Repl				738	20	2										
5 - Wood Door Set Repl - Pool Equip				1,599	20	1										
6 - Wood Door Set Repl - Clubhouse Back				8,991	20	9										
7 - Wood Door Set Repl - Clubhouse Front				8,991	20	9										
8 - Window Replace				9,552	30	1										
<b>BUILDING INTERIORS:</b>																
9 - Clubhouse Paint				3,279	7	3										
10 - Restroom Refurbish				57,030	30	1										
<b>FENCING &amp; WALLS:</b>																
11 - Arbor Paint & Repairs				7,711	5	1										
12 - Arbor Minor Repair				15,483	5	1										
13 - Arbor Major Repairs				77,414	20	11										
14 - Chain Link Repair				3,440	15	1										
15 - Metal Picker Paint				14,446	5	2										
16 - Metal Picker Repair				5,815	5	2										
17 - Metal Picker Replace				38,766	25	12										
18 - Monument Repair				3,507	10	3										
19 - Stucco Seat Wall Paint				1,317	10	1										
20 - Stucco Seat Wall Repair				2,197	10	1										
21 - Stucco Wall Paint				2,492	10	1										
22 - Stucco Wall Repair 6'				8,843	10	1										
<b>FLOORING:</b>																
23 - Clubhouse Tile Flooring				9,407	18	13										
<b>FURNISHINGS &amp; APPLIANCES:</b>																
24 - BBQ Replace				2,388	15	2										
25 - Clubhouse Furnishings				2,630	10	2										
26 - Dishwasher Replace				896	18	2										
27 - Refrigerator Replace				2,149	15	2										
28 - Microwave Replace				597	15	2										
29 - Stove/Oven Replace				2,630	20	2										
30 - Kitchen Countertop/Cabinet Repl				5,796	30	2										
31 - Metal Bench Repl - Tennis				2,157	20	3										
32 - Pool/Patio Furnishings				21,588	7	5										
33 - Picnic Bench Refinish				955	5	1										
34 - Picnic Bench Replace				2,269	15	6										
35 - Umbrella Replace				2,677	10	7										
36 - Wood Bench Refinish				1,194	5	1										
37 - Wood Bench Replace				3,552	15	6										

## Projected Expenditures

Assumed Annual Inflation Rate.....	3.0%	Current Repair Cost	Estimated Usfl Life	Fiscal Year Jan 1 .... Dec 31 ....	(1) 2022 2023	(2) 2023 2023	(3) 2024 2024	(4) 2025 2025	(5) 2026 2026	(6) 2027 2027	(7) 2028 2028	(8) 2029 2029	(9) 2030 2030	(10) 2031 2031
RESERVE COMPONENTS	%	Repair Cost												
<b>LANDSCAPING:</b>														
38 - Backflow Devices	33%	9,688	10	3										
39 - Irrigation Timers	1.5%	2,936	5	3										
40 - Irrigation Valves	5%	2,512	2	3										
41 - Plant Stock		4,384	5	3										
42 - Tree Stock		6,137	5	3										
<b>LIGHT FIXTURES:</b>														
43 - Bridgeway Lighting		28,600	20	5										
44 - Ext. Lantern Fixture Replace		398	20	6										
45 - Ext. Wall Mount Fixture Replace		716	20	6										
46 - Int. Recessed Light Fixture Repl		675	25	14										
47 - Int. Light Fixture Restroom Repl		450	25	1										
48 - Miscellaneous Lights		4,910	20	3										
49 - Spot Light Fixture Replace - Arbor		225	20	6										
<b>MECHANICAL SYSTEMS - HVAC:</b>														
50 - Air Conditioning Unit		9,826	15	8										
51 - Forced Air Furnace		5,476	15	4										
<b>MECHANICAL SYSTEMS - WATER:</b>														
52 - Water Heater Replace		1,578	15	1										
<b>PAVED SURFACES:</b>														
53 - Asphalt Repair/Replace	20%	5,404	10	6										
54 - Asphalt Sealcoat & Repair		4,635	5	1										
55 - Concrete Curb & Walkway Reprs		2,630	5	1										
56 - Pool Deck Repairs		5,261	20	1										
57 - Sport Court Repair	15%	3,194	10	1										
58 - Sport Court Sealcoat		1,596	5	1										
59 - Tennis Court Overlay		41,616	15	3										
60 - Tennis Court Colorcoat		10,944	5	3										
<b>RECREATION FACILITIES:</b>														
61 - Shower & Tile Repair		9,121	10	4										
62 - Shower & Tile Replace		25,185	20	8										
63 - Sport Court Fixtures		2,395	15	8										
64 - Tennis Court Nets		443	10	3										
65 - Tennis Court Windscreen Repl		5,130	20	13										
<b>RECREATION FACILITIES - POOL:</b>														
66 - Chlorinator Replace		587	5	1										
67 - Filter Replace		9,326	10	8										
68 - Heater Replace		117,745	8	1										
69 - Heater Replace		8,872	8	1										
70 - Pump Replace		2,610	5	1										
71 - Resurface Pool Interior		95,513	15	1										
72 - Tile & Coping Replace		9,062	15	1										

## Projected Expenditures

RESERVE COMPONENTS	Repair %	Current Repair Cost	Estimated Useful Life	Fiscal Year Jan 1 .... Dec 31 ....	(1) 2022	(2) 2023	(3) 2024	(4) 2025	(5) 2026	(6) 2027	(7) 2028	(8) 2029	(9) 2030	(10) 2031
<b>RECREATION FACILITIES -SPA:</b>														
73 - Chlorinator Replace		587	5	1	587									
74 - Filter Replace		2,574	10	7										
75 - Heater Replace		8,872	8	1	8,872									
76 - Pump Replace		1,343	5	3										
77 - Resurface Spa Interior		8,350	10	1	8,350									
78 - Tile & Coping Replace		1,463	15	1										
<b>ROOFING SYSTEM:</b>														
79 - Gutters & Downspouts		2,876	25	1										
80 - Roof Inspection & Repairs		908	5	1										
81 - Tile Roof Replacement		19,672	50	22										
<b>OTHER:</b>														
82 - Dog Station Replace		1,015	14	2										
83 - Drinking Fountain Replace		1,957	15	1										
84 - Future Energy Initiative (2025 only)		41,527	10	4										
85 - Reserve Study Update														
86 - Reserve Study Update Inspection														
<b>UNSCHEDULED</b>	<b>5%</b>	<b>2,446</b>	<b>1</b>	<b>1</b>										
<b>TOTAL EXPENDITURES</b>		<b>798,557</b>			<b>324,320</b>	<b>43,092</b>	<b>104,172</b>	<b>64,646</b>	<b>62,863</b>	<b>63,490</b>	<b>37,525</b>	<b>93,398</b>	<b>75,570</b>	<b>9,256</b>

Funding is addressed via the association's operating budget.

Funding is addressed via the association's operating budget.

2,446      2,818      3,100      3,317      3,549

3,798      4,064      4,348      4,652      4,978

# Projected Expenditures

Assumed Annual Inflation Rate.....	3.0%	Current Repair/Rep. % Cost	Estimated Usf Life	Fiscal Year Jan 1 .... Dec 31 .....	(11) 2032 2032	(12) 2033 2033	(13) 2034 2034	(14) 2035 2035	(15) 2036 2036	(16) 2037 2037	(17) 2038 2038	(18) 2039 2039	(19) 2040 2040	(20) 2041 2041
RESERVE COMPONENTS														
<b>BUILDING EXTERIORS:</b>														
1 - Stucco Sliding Paint		22.810	10	1										
2 - Stucco Sliding/Trim Repair	5%	8,502	10	1										
3 - Exterior Restroom Doors		1,414	25	3										
4 - Wood Doors Repl		738	20	2										
5 - Wood Door Set Repl - Pool Equip		1,599	20	1										
6 - Wood Door Set Repl - Clubhouse Back		8,991	20	9										
7 - Wood Door Set Repl - Clubhouse Front		8,991	20	9										
8 - Window Replace		9,552	30	1										
<b>BUILDING INTERIORS:</b>														
9 - Clubhouse Paint		3,279	7	3										
10 - Restroom Refurbish		57,030	30	1										
<b>FENCING &amp; WALLS:</b>														
11 - Arbor Paint & Repairs		7,711	5	1										
12 - Arbor Minor Repair	20%	15,483	5	1										
13 - Arbor Major Repairs		77,414	20	11										
14 - Chain Link Repair		3,440	15	1										
15 - Metal Picket Paint		14,446	5	2										
16 - Metal Picket Repair		5,815	5	2										
17 - Metal Picket Replace		38,766	25	12										
18 - Monument Repair		3,507	10	3										
19 - Stucco Seat Wall Paint		1,317	10	1										
20 - Stucco Seat Wall Repair		2,197	10	1										
21 - Stucco Wall Paint		2,492	10	1										
22 - Stucco Wall Repair 6'		8,843	10	1										
<b>FLOORING:</b>														
23 - Clubhouse Tile Flooring		9,407	18	13										
<b>FURNISHINGS &amp; APPLIANCES:</b>														
24 - BBQ Replace		2,388	15	2										
25 - Clubhouse Furnishings		2,630	10	2										
26 - Dishwasher Replace		836	18	2										
27 - Refrigerator Replace		2,149	15	2										
28 - Microwave Replace		597	15	2										
29 - Stove/Oven Replace		2,650	20	2										
30 - Kitchen Countertop/Cabinet Repl		5,796	30	2										
31 - Metal Bench Repl - Tennis		2,157	20	3										
32 - Pool Patio Furnishings		21,588	7	5										
33 - Picnic Bench Refinish		955	5	1										
34 - Picnic Bench Replace		2,269	15	6										
35 - Umbrella Replace		2,677	10	7										
36 - Wood Bench Refinish		1,194	5	1										
37 - Wood Bench Replace		3,582	15	6										

1,570  
3,449  
958  
1,4688  
4,296  
1,860  
5,261

## Projected Expenditures

RESERVE COMPONENTS		Repair %	Current Repair/Replace Cost	Estimated Usf Life	Fiscal Year Jan 1 ....	(11) 2032	(12) 2033	(13) 2034	(14) 2035	(15) 2036	(16) 2037	(17) 2038	(18) 2039	(19) 2040	(20) 2041
<b>LANDSCAPING:</b>															
38 - Backflow Devices		33%	9,688	10	3										
39 - Irrigation Timers		15%	2,936	5	3										
40 - Irrigation Valves		5%	2,512	2	3										
41 - Plant Stock			4,384	5	3										
42 - Tree Stock			6,137	5	3										
<b>LIGHT FIXTURES:</b>															
43 - Bridgeway Lighting			28,600	20	5										
44 - Ext. Latern Fixture Replace			398	20	6										
45 - Ext. Wall Mount Fixture Replace			716	20	6										
46 - Int. Recessed Light Fixture Repl			675	25	14										
47 - Int. Light Fixture Restroom Repl			450	25	1										
48 - Miscellaneous Lights			4,910	20	3										
49 - Spot Light Fixture Replace - Arbor			225	20	6										
<b>MECHANICAL SYSTEMS - HVAC:</b>															
50 - Air Conditioning Unit			9,826	15	8										
51 - Forced Air Furnace			5,476	15	4										
<b>MECHANICAL SYSTEMS - WATER:</b>															
52 - Water Heater Replace			1,578	15	1										
<b>PAVED SURFACES:</b>															
53 - Asphalt Repair/Replace		20%	5,404	10	6										
54 - Asphalt Sealcoat & Repair			4,635	5	1										
55 - Concrete Curb & Walkway Reprs			2,630	5	1										
56 - Pool Deck Repairs			5,261	20	1										
57 - Sport Court Repair		15%	3,194	10	1										
58 - Sport Court Sealcoat			1,536	5	1										
59 - Tennis Court Overlay			41,616	15	3										
60 - Tennis Court Colorcoat			10,944	5	3										
<b>RECREATION FACILITIES:</b>															
61 - Shower & Tile Repair			9,121	10	4										
62 - Shower & Tile Replace			25,185	20	8										
63 - Sport Court Pictures			2,325	15	8										
64 - Tennis Court Nets			443	10	3										
65 - Tennis Court Windscreen Repl			5,150	20	13										
<b>RECREATION FACILITIES - POOL:</b>															
66 - Chlorinator Replace			587	5	1										
67 - Filter Replace			9,326	10	8										
68 - Heater Replace			17,745	8	1										
69 - Heater Replace			8,872	8	1										
70 - Pump Replace			2,610	5	1										
71 - Resurface Pool Interior			95,513	15	1										
72 - Tile & Coping Replace			9,062	15	1										

### Projected Expenditures

## Projected Expenditures

Assumed Annual Inflation Rate.....	3.0%	Current Repair Cost	Estimated Usf Life	Fiscal Year Jan 1 .... Dec 31 ....	(21)	(22)	(23)	(24)	(25)	(26)	(27)	(28)	(29)	(30)
RESERVE COMPONENTS	%	Repair Cost	Reprl Cost		2042	2043	2044	2045	2046	2047	2048	2049	2050	2051
<b>BUILDING EXTERIORS:</b>														
1 - Stucco Siding Paint		22,810	10	1	41,197									
2 - Stucco Siding/Trim Repair	5%	8,502	10	1	15,355									
3 - Exterior Restroom Doors		1,414	25	3										
4 - Wood Doors Repl		738	20	2										
5 - Wood Door Set Repl - Pool Equip		1,599	20	1										
6 - Wood Door Set Repl - Clubhouse Back		8,991	20	9										
7 - Wood Door Set Repl - Clubhouse Front		8,991	20	9										
8 - Window Replace		9,552	30	1										
<b>BUILDING INTERIORS:</b>														
9 - Clubhouse Paint		3,279	7	3										
10 - Restroom Refurbish		57,030	30	1										
<b>FENCING &amp; WALLS:</b>														
11 - Arbor Paint & Repairs		7,711	5	1										
12 - Arbor Minor Repair		15,483	5	1										
13 - Arbor Major Repairs		77,414	20	11										
14 - Chain Link Repair		3,440	15	1										
15 - Metal Picket Paint		14,446	5	2										
16 - Metal Picket Repair		5,815	5	2										
17 - Metal Picket Replace		38,766	25	12										
18 - Monument Repair		3,507	10	3										
19 - Stucco Seat Wall Paint		1,317	10	1										
20 - Stucco Seat Wall Repair		2,197	10	1										
21 - Stucco Wall Paint		2,492	10	1										
22 - Stucco Wall Repair 6'		8,843	10	1										
<b>FLOORING:</b>														
23 - Clubhouse Tile Flooring		9,407	18	13										
<b>FURNISHINGS &amp; APPLIANCES:</b>														
24 - BBQ Replace		2,388	15	2										
25 - Clubhouse Furnishings		2,630	10	2										
26 - Dishwasher Replace		896	18	2										
27 - Refrigerator Replace		2,149	15	2										
28 - Microwave Replace		597	15	2										
29 - Stove/Oven Replace		2,650	20	2										
30 - Kitchen Countertop/Cabinet Repl		5,796	30	2										
31 - Metal Bench Repl - Tennis		2,157	20	3										
32 - Pool Patio Furnishings		21,588	7	5										
33 - Picnic Bench Refinish		955	5	1										
34 - Picnic Bench Replace		2,269	15	6										
35 - Umbrella Replace		2,677	10	7										
36 - Wood Bench Refinish		1,194	5	1										
37 - Wood Bench Replace		3,532	15	6										

## Projected Expenditures

Assumed Annual Inflation Rate.....	3.0%	Current Repair/Replace Cost	Estimated Useful Life	Fiscal Year Jan 1 .... Dec 31 .....	(21)	(22)	(23)	(24)	(25)	(26)	(27)	(28)	(29)	(30)
RESERVE COMPONENTS	%	Repair Cost			2042	2043	2044	2045	2046	2047	2048	2049	2050	2051
<b>LANDSCAPING:</b>														
38 - Backflow Devices	33%	9,688	10	3										
39 - Irrigation Timers	15%	2,936	5	3										
40 - Irrigation Valves	5%	2,512	2	3										
41 - Plant Stock		4,384	5	3										
42 - Tree Stock		6,137	5	3										
<b>LIGHT FIXTURES:</b>														
43 - Bridgeway Lighting		28,600	20	5										
44 - Ext. Latern Fixture Replace		398	20	6										
45 - Ext. Wall Mount Fixture Replace		716	20	6										
46 - Int. Recessed Light Fixture Repl		675	25	14										
47 - Int. Light Fixture Restroom Repl		450	25	1										
48 - Miscellaneous Lights		4,910	20	3										
49 - Spot Light Fixture Replace - Arbor		225	20	6										
<b>MECHANICAL SYSTEMS - HVAC:</b>														
50 - Air Conditioning Unit		9,826	15	8										
51 - Forced Air Furnace		5,476	15	4										
<b>MECHANICAL SYSTEMS - WATER:</b>														
52 - Water Heater Replace		1,578	15	1										
<b>PAVED SURFACES:</b>														
53 - Asphalt Repair/Replace	20%	5,404	10	6										
54 - Asphalt Sealcoat & Repair		4,635	5	1										
55 - Concrete Curb & Walkway Reps		2,630	5	1										
56 - Pool Deck Repairs		5,261	20	1										
57 - Sport Court Repair	15%	3,194	10	1										
58 - Sport Court Sealcoat		1,536	5	1										
59 - Tennis Court Overlay		41,616	15	3										
60 - Tennis Court Colorcoat		10,944	5	3										
<b>RECREATION FACILITIES:</b>														
61 - Shower & Tile Repair		9,121	10	4										
62 - Shower & Tile Replace		25,185	20	8										
63 - Sport Court Fixtures		2,325	15	8										
64 - Tennis Court Nets		443	10	3										
65 - Tennis Court Windscreen Repl		5,130	20	13										
<b>RECREATION FACILITIES - POOL:</b>														
66 - Chlorinator Replace		587	5	1										
67 - Filter Replace		9,326	10	8										
68 - Heater Replace		17,745	8	1										
69 - Heater Replace		8,872	8	1										
70 - Pump Replace		2,610	5	1										
71 - Resurface Pool Interior		95,513	15	1										
72 - Tile & Coping Replace		9,062	15	1										

### Projected Expenditures

## Funding Plan

### Projected Cash Balance

		Fiscal Year			Expenditures (inflated \$)			Reserve Contribution			Special Assessments (\$ or Loan)			Interest			Ending Balance		
		(1)	(2)	(3)	(4)	(5)	(6)	(7)	(8)	(9)	(10)	(11)	(12)	(13)	(14)	(15)	(16)		
Jan 1 ....		2022	2023	2024	2025	2026	2027	2028	2029	2030	2031								
Dec 31 ....		2022	2023	2024	2025	2026	2027	2028	2029	2030	2031								
<b>BEGINNING BALANCE</b>																			
EXPENDITURES (inflated \$)	3.0%	324,320	43,092	104,172	64,646	62,863	63,490	37,525	93,398	75,570	9,256								
RESERVE CONTRIBUTION		48,928	56,365	62,001	66,341	70,985	75,954	81,271	86,960	93,047	99,560								
Per Unit Per Month (375 units)		10.87	12.53	13.78	14.74	15.77	16.88	18.06	19.32	20.68	22.12								
Percentage Increase to Reserves		15.2	15.2	10.0	7.0	7.0	7.0	7.0	7.0	7.0	7.0								
SPECIAL ASSESSMENTS (\$ or LOAN)		0	0	0	0	0	0	0	0	0	0								
INTEREST	0.1%	89	24	17	6	9	14	28	37	40	67								
<b>ENDING BALANCE</b>		40,897	54,194	12,040	13,742	21,873	34,351	78,124	71,724	89,241	179,612								

## Funding Plan

---

### Projected Cash Balance

	(11)	(12)	(13)	(14)	(15)	(16)	(17)	(18)	(19)	(20)
Jan 1 .....	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
Dec 31 .....	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041
<b>BEGINNING BALANCE</b>	<b>179,612</b>	<b>43,631</b>	<b>36,707</b>	<b>72,144</b>	<b>120,800</b>	<b>249,750</b>	<b>145,120</b>	<b>181,659</b>	<b>251,404</b>	<b>378,894</b>
<b>EXPENDITURES (inflated \$)</b>	<b>3.0%</b>	<b>242,566</b>	<b>120,931</b>	<b>86,556</b>	<b>81,895</b>	<b>10,781</b>	<b>254,142</b>	<b>123,415</b>	<b>133,144</b>	<b>56,939</b>
<b>RESERVE CONTRIBUTION</b>	<b>106,530</b>	<b>113,987</b>	<b>121,966</b>	<b>130,503</b>	<b>139,639</b>	<b>149,413</b>	<b>159,872</b>	<b>127,898</b>	<b>131,735</b>	<b>135,687</b>
Per Unit Per Month (375 units)	23.67	25.33	27.10	29.00	31.03	33.20	35.53	28.42	29.27	30.15
Percentage Increase to Reserves	7.0	7.0	7.0	7.0	7.0	7.0	7.0	(20.0)	3.0	3.0
<b>SPECIAL ASSESSMENT(S) or LOAN</b>	<b>0</b>									
<b>INTEREST</b>	<b>0.1%</b>	<b>56</b>	<b>20</b>	<b>27</b>	<b>48</b>	<b>93</b>	<b>99</b>	<b>82</b>	<b>90</b>	<b>107</b>
<b>ENDING BALANCE</b>	<b>43,631</b>	<b>36,707</b>	<b>72,144</b>	<b>120,800</b>	<b>249,750</b>	<b>145,120</b>	<b>181,659</b>	<b>176,502</b>	<b>251,404</b>	<b>378,894</b>

## Funding Plan

---

Projected Cash Balance									
	(21)	(22)	(23)	(24)	(25)	(26)	(27)	(28)	(29)
Jan 1 ....	2042	2043	2044	2045	2046	2047	2048	2049	2050
Dec 31 .....	2042	2043	2044	2045	2046	2047	2048	2049	2051
<b>BEGINNING BALANCE</b>									
	378,894	309,868	361,342	385,286	424,141	438,403	444,813	543,158	569,743
<b>EXPENDITURES (Inflated \$)</b>									
	3.0%	208,955	92,644	124,511	114,065	143,251	155,827	68,780	145,578
<b>RESERVE CONTRIBUTION</b>									
	139,757	143,950	148,269	152,717	157,298	162,017	166,878	171,884	177,040
Per Unit Per Month (375 units)									
Percentage Increase to Reserves									
SPECIAL ASSESSMENT(S) or LOAN									
INTEREST									
<b>ENDING BALANCE</b>									
	309,868	361,342	385,286	424,141	438,403	444,813	543,158	569,743	691,359
									862,590

# Component Quantification

RESERVE COMPONENTS	Assumed Annual Inflation Rate.....	3.0%	Current Rep/Rpl Cost	Estimated Usfl Life	Quantity	Unit of Measurement	Unit Cost	Notes
<b>BUILDING EXTERIORS:</b>								
1 - Stucco Siding Paint			22,810	10	1	17,280 square feet	1.32	
2 - Stucco Siding/Trim Repair	5%		8,502	10	1	17,280 square feet	9.84	Allows 5% of this component to be repaired every 10 years.
3 - Exterior Restroom Doors			1,414	25	3	2 doors	707.18	Two restroom doors.
4 - Wood Doors Repl			738	20	2	2 doors	368.96	Two doors lead to outside from clubhouse.
5 - Wood Door Set Repl - Pool Equip			1,599	20	1	2 sets	799.42	
6 - Wood Door Set Repl - Clubhouse Back			8,991	20	9	1 set	8,990.80	Located at the clubhouse double doors
7 - Wood Door Set Repl - Clubhouse Front			8,991	20	9	1 set	8,990.80	Located at the clubhouse double doors
8 - Window Replace			9,552	30	1	1 fund	9,552.42	
<b>BUILDING INTERIORS:</b>								
9 - Clubhouse Paint			3,279	7	3	1,744 square feet	1.88	
10 - Restroom Refurbish			57,030	30	1	1 fund	57,030.44	Includes flooring.
<b>FENCING &amp; WALLS:</b>								
11 - Arbor Paint & Repairs			7,711	5	1	1,260 square feet	6.12	
12 - Arbor Minor Repair	20%		15,483	5	1	1,260 square feet	61.44	Allows 20% of this component to be repaired/replaced every 5 years.
13 - Arbor Major Repairs			77,414	20	11	1,260 square feet	61.44	Includes trellis at gate entry. (Major Rpr's \$30K in 2012)
14 - Chain Link Repair			3,440	15	1	980 linear feet	3.51	
15 - Metal Picket Paint			14,446	5	2	7,296 linear feet	1.98	
16 - Metal Picket Repair	15%		5,815	5	2	608 linear feet	63.76	Allows 15% of this component to be repaired every 10 years.
17 - Metal Picket Replace			38,766	25	12	608 linear feet	63.76	
18 - Monument Repair			3,507	10	3	2 units	1,753.51	
19 - Stucco Seat Wall Paint			1,317	10	1	736 square feet	1.79	
20 - Stucco Seat Wall Repair			2,197	10	1	184 linear feet	119.41	Allows 10% of this component to be repaired every 10 years.
21 - Stucco Wall Paint			2,492	10	1	1,392 square feet	1.79	
22 - Stucco Wall Repair 6'	10%		8,843	10	1	116 linear feet	762.36	Includes metal coping at top of wall.
<b>FLOORING:</b>								
23 - Clubhouse Tile Flooring			9,407	18	13	61 square yards	154.22	
<b>FURNISHINGS &amp; APPLIANCES:</b>								
24 - BBQ Replace			2,388	15	2	1 grill	2,388.10	
25 - Clubhouse Furnishings			2,630	10	2	1 set	2,630.26	
26 - Dishwasher Replace			896	18	2	1 dishwasher	895.54	
27 - Refrigerator Replace			2,149	15	2	1 refrigerator	2,149.29	
28 - Microwave Replace			597	15	2	1 microwave	597.03	
29 - Stove/Oven Replace			2,630	20	2	1 oven/stovetop	2,630.26	
30 - Kitchen Countertop/Cabinet Repl			5,796	30	2	1 fund	5,796.37	
31 - Metal Bench Repl - Tennis			2,157	20	3	2 benches	1,078.41	
32 - Pool Patio Furnishings			21,588	7	5	1 fund	21,588.45	
33 - Picnic Bench Refinish			955	5	1	2 benches	477.62	
34 - Picnic Bench Replace			2,269	15	6	2 benches	1,134.35	
35 - Umbrella Replace			2,677	10	7	7 umbrellas	382.45	
36 - Wood Bench Refinish			1,194	5	1	4 benches	298.51	
37 - Wood Bench Replace			3,582	15	6	4 benches	895.54	

# Component Quantification

RESERVE COMPONENTS	Assumed Annual Inflation Rate.....	3.0%	Current Repair/Replace Cost	Estimated Usd Life	Rmng Life	Quantity	Unit of Measurement	Unit Cost	Notes
	Repair %		Repair/Replace Cost	Usd Life	Life				
<b>LANDSCAPING:</b>									
38 - Backflow Devices	33%	9,688	10	3	9	devices	3,261.93	Information provided by Aragon Landscapers in 2013, estimates only.	
39 - Irrigation Timers	15%	2,936	5	3	10	timers	1,957.16	Information provided by Aragon Landscapers in 2013, estimates only.	
40 - Irrigation Valves	5%	2,512	2	3	110	valves	456.67	Information provided by Aragon Landscapers in 2013, estimates only.	
41 - Plant Stock		4,384	5	3	1	fund	4,383.77		
42 - Tree Stock		6,137	5	3	1	fund	6,137.27		
<b>LIGHT FIXTURES:</b>									
43 - Bridgeway Lighting		28,600	20	5	1	estimate fixtures	28,599.61		
44 - Ext. Latern. Fixture Replace		398	20	6	3	fixtures	132.61	2 Latern wall mount at entry to clubhouse, 1 Latern wall mount rear of clubhouse	
45 - Ext. Wall Mount Fixture Replace		716	20	6	5	fixtures	143.22		
46 - Int Recessed Light Fixture Repl		675	25	14	6	fixtures	112.55		
47 - Int. Light Fixture Restroom Repl		450	25	1	4	fixtures	112.55		
48 - Miscellaneous Lights		4,910	20	3	1	fund	4,909.82		
49 - SpotLight Fixture Replace - Arbor		225	20	6	2	fixtures	112.55		
<b>MECHANICAL SYSTEMS - HVAC:</b>									
50 - Air Conditioning Unit		9,826	15	8	1	unit	9,826.34		
51 - Forced Air Furnace		5,476	15	4	1	furnace	5,476.46		
<b>MECHANICAL SYSTEMS - WATER:</b>									
52 - Water Heater Replace		1,578	15	1	1	heater	1,578.16		
<b>PAVED SURFACES:</b>									
53 - Asphalt Repair/Replace	20%	5,404	10	6	5,653	square feet	4.78	Allows 20% of this component to be repaired every 10 years.	
54 - Asphalt Sealcoat & Repair		4,635	5	1	5,653	square feet	0.82		
55 - Concrete Curb & Walkway Reprs		2,630	5	1	1	fund	2,630.26		
56 - Pool Deck Repairs		5,261	20	1	1	fund	5,260.52		
57 - Sport Court Repair		3,194	10	1	4,200	square feet	5.07	Allows 15% of this component to be repaired every 10 years.	
58 - Sport Court Sealcoat		1,596	5	1	4,200	square feet	0.38		
59 - Tennis Court Overlay		41,616	15	3	14,400	square feet	2.89		
60 - Tennis Court Colorcoat		10,944	5	3	14,400	square feet	0.76		
<b>RECREATION FACILITIES:</b>									
61 - Shower & Tile Repair		9,121	10	4	1	location	9,120.92		
62 - Shower & Tile Replace		25,185	20	8	1	location	25,184.62		
63 - Sport Court Fixtures		2,325	15	8	1	fixture	2,325.37		
64 - Tennis Court Nets		443	10	3	2	nets	221.68		
65 - Tennis Court Windscreen Repl		5,130	20	13	1	fund	5,130.42		
<b>RECREATION FACILITIES - POOL:</b>									
66 - Chlorinator Replace		587	5	1	1	chlorinator filter	587.15	Information provided by Waves Above in 2013, estimates only.	
67 - Filter Replace		9,326	10	8	1	filter	9,325.57		
68 - Heater Replace		17,745	8	1	2	heaters	8,872.46	Information provided by Property Manager in 2013.	
69 - Heater Replace		8,872	8	1	1	heater	8,872.46	Information provided by Property Manager in 2013.	
70 - Pump Replace		2,610	5	1	1	pump	2,609.55	Information provided by Waves Above in 2013, estimates only.	
71 - Resurface Pool Interior		95,513	15	1	3,750	square feet	25.47		
72 - Tile & Coping Replace		9,062	15	1	253	linear feet	35.82		

## Component Quantification

RESERVE COMPONENTS	Assumed Annual Inflation Rate.....	Repair %	Current Rep/Rpl Cost	Estimated Usf Life	Rmng Life	Quantity	Unit of Measurement	Unit Cost	Notes
<b>RECREATION FACILITIES -SPA:</b>									
73 - Chlorinator Replace			587	5	1	1	chlorinator	587.15	Information provided by Waves Above in 2013, estimates only.
74 - Filter Replace			2,574	10	7	1	filter	2,574.01	Estimate #1012, Waves Above Pool Service 05/16/2018
75 - Heater Replace			8,872	8	1	1	heater	8,872.46	Information provided by Waves Above in 2013, estimates only.
76 - Pump Replace			1,343	5	3	1	pump	1,343.10	
77 - Resurface Spa Interior			8,350	10	1	80	square feet	104.38	
78 - Tile & Coping Replace			1,463	15	1	35	linear feet	41.79	
<b>ROOFING SYSTEM:</b>									
79 - Gutters & Downspouts			2,876	25	1	172	linear feet	16.72	
80 - Roof Inspection & Repairs			908	5	1	1,714	square feet	0.53	
81 - Tile Roof Replacement			19,672	50	22	1,714	square feet	11.48	
<b>OTHER:</b>									
82 - Dog Station Replace			1,015	14	2	1	fund	1,014.94	
83 - Drinking Fountain Replace			1,957	15	1	1	fund	1,957.16	
84 - Future Energy Initiative (2025 only)			41,527	10	4	1	fund	41,527.02	Funding is addressed via the association's operating budget.
85 - Reserve Study Update									Funding is addressed via the association's operating budget.
86 - Reserve Study Update Inspection									

## Accrued Liability

RESERVE COMPONENTS	Assumed Annual Inflation Rate.....	Repair %	Current Repair/Replace Cost	Estimated Usfl Life	Rmng Life	Annual Liability	Accrued Liability	Straight Line	Funding	PUMF	Proration Percentage	Annual Liability	Cash Flow Accrued Liability
<b>BUILDING EXTERIORS:</b>													
1 - Stucco Siding Paint	5%	22,810	10	1	2,281	20,529	3,30%	0.36	1,612	14,512			
2 - Stucco Siding/Trim Repair		8,502	10	1	850	7,652	1.23%	0.13	601	5,409			
3 - Exterior Restroom Doors		1,414	25	3	57	1,245	0.08%	0.01	40	880			
4 - Wood Doors Repl		738	20	2	37	664	0.05%	0.01	26	469			
5 - Wood Door Set Repl - Pool Equip		1,599	20	1	80	1,519	0.12%	0.01	57	1,074			
6 - Wood Door Set Repl - Clubhouse Back		8,991	20	9	450	4,945	0.65%	0.07	318	3,496			
7 - Wood Door Set Repl - Clubhouse Front		8,991	20	9	450	4,945	0.65%	0.07	318	3,496			
8 - Window Replace		9,552	30	1	318	9,234	0.46%	0.05	225	6,528			
<b>BUILDING INTERIORS:</b>													
9 - Clubhouse Paint		3,279	7	3	468	1,874	0.68%	0.07	331	1,324			
10 - Restroom Refurbish		57,030	30	1	1,901	55,129	2.75%	0.30	1,344	38,972			
<b>FENCING &amp; WALLS:</b>													
11 - Arbor Paint & Repairs	20%	7,711	5	1	1,542	6,169	2.23%	0.24	1,090	4,361			
12 - Arbor Minor Repair		15,483	5	1	3,097	12,386	4.47%	0.49	2,189	8,756			
13 - Arbor Major Repairs		77,414	20	11	3,871	34,836	5.59%	0.61	2,736	24,626			
14 - Chain Link Repair		3,440	15	1	229	3,210	0.33%	0.04	162	2,270			
15 - Metal Picket Paint		14,446	5	2	2,889	8,668	4.17%	0.45	2,042	6,127			
16 - Metal Picket Repair	15%	5,815	5	2	1,163	3,489	1.68%	0.18	822	2,466			
17 - Metal Picket Replace		38,766	25	12	1,551	20,158	2.24%	0.24	1,096	14,250			
18 - Monument Repair		3,507	10	3	351	2,455	0.51%	0.06	248	1,735			
19 - Stucco Seat Wall Paint		1,317	10	1	132	1,186	0.19%	0.02	93	838			
20 - Stucco Seat Wall Repair		2,197	10	1	220	1,977	0.32%	0.03	155	1,398			
21 - Stucco Wall Paint		2,492	10	1	249	2,243	0.36%	0.04	176	1,585			
22 - Stucco Wall Repair 6'	10%	8,843	10	1	884	7,959	1.28%	0.14	625	5,626			
<b>FLOORING:</b>													
23 - Clubhouse Tile Flooring		9,407	18	13	523	2,613	0.76%	0.08	369	1,847			
<b>FURNISHINGS &amp; APPLIANCES:</b>													
24 - BBQ Replace		2,388	15	2	159	2,070	0.23%	0.03	113	1,463			
25 - Clubhouse Furnishings		2,630	10	2	263	2,104	0.38%	0.04	186	1,487			
26 - Dishwasher Replace		896	18	2	50	796	0.07%	0.01	35	563			
27 - Refrigerator Replace		2,149	15	2	143	1,863	0.21%	0.02	101	1,317			
28 - Microwave Replace		597	15	2	40	517	0.06%	0.01	28	366			
29 - Stove/Oven Replace		2,630	20	2	132	2,367	0.19%	0.02	93	1,673			
30 - Kitchen Countertop/Cabinet Repl		5,796	30	2	193	5,410	0.28%	0.03	137	3,824			
31 - Metal Bench Repl - Tennis		2,157	20	3	108	1,833	0.16%	0.02	76	1,296			
32 - Pool Patio Furnishings		21,588	7	5	3,084	6,168	4.46%	0.48	2,180	4,360			
33 - Picnic Bench Refinish		955	5	1	191	764	0.28%	0.03	135	540			
34 - Picnic Bench Replace		2,269	15	6	151	1,361	0.22%	0.02	107	962			
35 - Umbrella Replace		2,677	10	7	268	803	0.39%	0.04	189	568			
36 - Wood Bench Refinish		1,194	5	1	239	955	0.35%	0.04	169	675			
37 - Wood Bench Replace		3,582	15	6	239	2,149	0.35%	0.04	169	1,519			

## Accrued Liability

RESERVE COMPONENTS	Assumed Annual Inflation Rate.....	Repair %	Current Repri/Repl Cost	Estimated Usf Life	Annual Running Liability	Straight Line Accrued Liability	Proration Percentage	PUPM Funding	Cash Flow	
									Annual Liability	Accrued Liability
<b>LANDSCAPING:</b>										
38 - Backflow Devices	33%	9,688	10	3	969	6,782	1.40%	0.15	685	4,794
39 - Irrigation Timers	15%	2,936	5	3	587	1,174	0.85%	0.09	415	830
40 - Irrigation Valves	5%	2,512	2	3	1,256	0	1.81%	0.20	888	0
41 - Plant Stock	4,384	5	3	877	1,754	1.27%	0.14	620	1,240	
42 - Tree Stock	6,137	5	3	1,227	2,455	1.77%	0.19	868	1,735	
<b>LIGHT FIXTURES:</b>										
43 - Bridgeway Lighting	28,600	20	5	1,430	21,450	2.07%	0.22	1,011	15,163	
44 - Ext. Latern Fixture Replace	398	20	6	20	278	0.03%	0.00	14	197	
45 - Ext. Wall Mount Fixture Replace	716	20	6	36	501	0.05%	0.01	25	354	
46 - Int. Recessed Light Fixture Repl	675	25	14	27	297	0.04%	0.00	19	210	
47 - Int. Light Fixture Restroom Repl	450	25	1	18	432	0.03%	0.00	13	306	
48 - Miscellaneous Lights	4,910	20	3	245	4,173	0.35%	0.04	174	2,950	
49 - Spot Light Fixture Replace - Arbor	225	20	6	11	158	0.02%	0.00	8	111	
<b>MECHANICAL SYSTEMS - HVAC:</b>										
50 - Air Conditioning Unit	9,826	15	8	655	4,586	0.95%	0.10	463	3,242	
51 - Forced Air Furnace	5,476	15	4	365	4,016	0.53%	0.06	258	2,839	
<b>MECHANICAL SYSTEMS - WATER:</b>										
52 - Water Heater Replace	1,578	15	1	105	1,473	0.15%	0.02	74	1,041	
<b>PAVED SURFACES:</b>										
53 - Asphalt Repair/Replace	20%	5,404	10	6	540	2,162	0.78%	0.08	382	1,528
54 - Asphalt Sealcoat & Repair	4,635	5	1	927	3,708	1.34%	0.15	655	2,621	
55 - Concrete Curb & Walkway Reprs	2,630	5	1	526	2,04	0.76%	0.08	372	1,887	
56 - Pool Deck Repairs	5,261	20	1	263	4,997	0.38%	0.04	186	3,533	
57 - Sport Court Repair	3,194	10	1	319	2,875	0.46%	0.05	226	2,032	
58 - Sport Court Sealcoat	1,596	5	1	319	1,277	0.46%	0.05	226	903	
59 - Tennis Court Overlay	41,616	15	3	2,774	33,293	4.01%	0.44	1,961	23,535	
60 - Tennis Court Colorcoat	10,944	5	3	2,189	4,378	3.18%	0.34	1,547	3,095	
<b>RECREATION FACILITIES:</b>										
61 - Shower & Tile Repair	9,121	10	4	912	5,473	1.32%	0.14	645	3,869	
62 - Shower & Tile Replace	25,185	20	8	1,259	15,111	1.82%	0.20	890	10,682	
63 - Sport Court Features	2,325	15	8	155	1,085	0.22%	0.02	110	767	
64 - Tennis Court Nets	443	10	3	44	310	0.06%	0.01	31	219	
65 - Tennis Court Windscreen Repl	5,130	20	13	257	1,796	0.37%	0.04	181	1,269	
<b>RECREATION FACILITIES - POOL:</b>										
66 - Chlorinator Replace	587	5	1	117	470	0.17%	0.02	83	332	
67 - Filter Replace	9,326	10	8	933	1,865	1.35%	0.15	659	1,318	
68 - Heater Replace	17,745	8	1	2,218	15,327	3.20%	0.35	1,568	10,976	
69 - Heater Replace	8,872	8	1	1,109	7,763	1.60%	0.17	784	5,488	
70 - Pump Replace	2,610	5	1	522	2,088	0.75%	0.08	369	1,476	
71 - Resurface Pool Interior	95,513	15	1	6,368	89,145	9.28%	1.00	4,501	63,018	
72 - Tile & Coping Replace	9,062	15	1	604	8,458	0.87%	0.09	427	5,979	

## Accrued Liability

RESERVE COMPONENTS	Repair %	Current Rep/Rpl Cost	Estimated Usfl Life	Rmng Life	Annual Accrued Liability	Straight Line Accrued Liability	PUM Funding	Proration Percentage	Cash Flow Annual Liability	Accrued Liability
<b>RECREATION FACILITIES -SPA:</b>										
73 - Chlorinator Replace	587	5	1	117	470	0.17%	0.02	83	332	
74 - Filter Replace	2,574	10	7	257	772	0.37%	0.04	182	546	
75 - Heater Replace	8,872	8	1	1,109	7,763	1.60%	0.17	784	5,488	
76 - Pump Replace	1,343	5	3	269	537	0.39%	0.04	190	380	
77 - Resurface Spa Interior	8,350	10	1	835	7,515	1.21%	0.13	590	5,313	
78 - Tile & Coping Replace	1,463	15	1	98	1,365	0.14%	0.02	69	965	
<b>ROOFING SYSTEM:</b>										
79 - Gutters & Downspouts	2,876	25	1	115	2,761	0.11%	0.02	81	1,952	
80 - Roof Inspection & Repairs	908	5	1	182	727	0.26%	0.03	128	514	
81 - Tile Roof Replacement	19,672	50	22	393	11,016	0.57%	0.06	278	7,788	
<b>OTHER:</b>										
82 - Dog Station Replace	1,015	14	2	72	870	0.10%	0.01	51	615	
83 - Drinking Fountain Replace	1,957	15	1	130	1,827	0.19%	0.02	92	1,291	
84 - Future Energy Initiative (2025 only)	41,527	10	4	4,153	24,916	6.00%	0.65	2,936	17,614	
85 - Reserve Study Update										
86 - Reserve Study Update Inspection UNSCHEDULED.....	5%	2,446	1	1	2,446	0	3.53%	0.38	1,729	0
					69,213	558,199	100%	10.87	48,928	394,598
		798,557								